





Installation Instructions

Work Tag
WWT




203733 Rev A

To erase and relabel, simply wet and wipe away.



On Organizational Worktools



On Hanging Folders



Wet-Erase Surface

For a better day at work.™

details®

A STEELCASE COMPANY

www.details-worktools.com


P.O. Box 1967 Grand Rapids, MI 49501-1967

All rights reserved. Printed in U.S.A. 3/10




Installation Instructions

Work Tag
WWT




203733 Rev A


To erase and relabel, simply wet and wipe away.



On Organizational Worktools



On Hanging Folders



Wet-Erase Surface

For a better day at work.™

details®

A STEELCASE COMPANY

www.details-worktools.com

P.O. Box 1967 Grand Rapids, MI 49501-1967

All rights reserved. Printed in U.S.A. 3/10